




Guide Bush with Centring Collar

Code: **G31**



d1	l1	d2	d3	k	l2
15	17	20	25	6	9
	22				
	27				
	36				
	46				
	56				
	66				
	76				
18	86	26	31	6	9
	96				
	116				
	17				
	22				
	27				
	36				
	46				
22	56	30	35	6	9
	66				
	76				
	86				
	96				
	106				
	116				
	136				
24	156	30	35	6	9
	17				
	22				
	27				
	36				
	46				
	56				
	66				
30	76	42	47	6	9
	86				
	96				
	106				
	116				
	126				
	136				
	156				
40	196	54	60	10	12
	246				




Code: **G31**

d1	l1	d2	d3	k	l2
15	27	42	47	6	9
	36				
	46				
	56				
	66				
	76				
	86				
	96				
18	106	42	47	6	9
	116				
	126				
	136				
	156				
	196				
	246				



Centring Bush

Code: **G28**



Order: **G28. d2 x l**
Material: 1.7131 - Hardness: 58 - 62 HRC

Code: **G28**

d2	l1	d1	d3	l2			
20	30	16	M8	2.5			
	40						
	60						
	80						
	100						
	120						
26	140	21	M10	2.5			
	160						
	180						
	30				25	M12	4.5
	40						
	60						
80							
100							
120							
30	140	33	M12	4.5			
	160						
	180						
	200						
	240						
	260						
42	300	43	M12	4.5			
	60						
	80						
	120						
	160						
	200						
54	240	43	M12	4.5			
	280						

Order: **G31. d1 x l1**

Material: 1.7131 - Hardness: 58 - 62 HRC